K P SKEITES QUALITY CLEANING SERVICES EST.1978



COMPANY REGISTRATION NUMBER: 4917772

## **HEALTH & SAFTETY WORKING MANDATE RISK ASSESSMENT**

## **POTENTIAL 5 RISKS HAZARDS**

- 1. Risking ladder footing out to far without someone on the bottom or tied.
- 2. Leaving ladder vertical and erected in strong winds and not present.
- 3. Do not put ladder onto slippery surface what may be caused by Frosts, snow, moss or other ways risky.
- 4. Making sure ladder is correctly made as safe as possible when resting against property for climbing.

Do not carry ladders around blind corners without shouting ladder coming and keeping foot of ladder vertical or upright when carrying to position of work.

## **PRECAUTIONS & CONTROLS**

- 1. Evaluating the risks to reduce this is inspection of property for dangers that could arise.
- 2. Evaluating the leavels and areas of ground for erection of ladder.
- 3. Safety awareness signs in place to make public aware of work and dangers are in progress.
- **4.** Making sure of overhanging dangers such as power cables, BT lines and ground, etc. Also ground level vehicles and obstructions.
- 5. To tie off ladder and make fixed when required and erect bollard sign to make public aware.

## METHOD OF STATEMENT OF HOW TO CARRY OUT WINDOW CLEANING

By method of using upright ladder to make sure of awareness and dangers when carrying out the cleaning of windows or plastic preferably as above. By using of a sponge mop and blade, bucket, belt with holder for sponge mop and blade and cloths. To climb ladder in correct way and use in the right position safely and tie if necessary, when danger may arise, especially when wind and slippery surfaces adjacent to working areas. When leaving the ladder unattended always tie, remove from property or lay down ladder so it's unutilized from causing any danger. When ladder is not in use make sure it is clamped down on vehicle before making area safe for public, site or company employees

**KPSKEITES QUALITY CLEANING SEVICES**